


# Wasp Wing 2 Pro / 蜂翼2 Pro

Swirl Exhaustion, Stepless Cooling

漩涡排气 无级制冷



Hold the mobile phone in your hand and push up against the upper pull hook  
手持手机, 抵住上拉钩向上推



Connect the power supply and toggle the switch to ON  
连接电源, 拨动开关至ON



Scan the QR code on the left, download Flydigi Game Center connect the Wasp Wing 2 pro , and enable the following features.

**1. Infinitely adjustable**

Freely adjustable cooling speed

**2. Dazzling light switch**

Control lights on or off

**3. Temperature monitor**

Monitor mobile phone temperature (support Android only) , monitor temperature of the Wasp Wing 2 Pro(support both Android and IOS)

扫描左侧二维码, 下载飞智游戏厅, 连接蜂翼2pro, 开启以下功能:

**1. 无极调节**

可自由调节制冷效果

**2. 炫彩灯开关**

控制灯的开启或关闭

**3. 温度监控**

监控手机温度 (仅安卓支持)

监控散热器冷面的温度 (安卓、苹果都支持)



Scan the QR code on the left to enter the FLYDIGI official website for more product information and services.

扫描左侧二维码, 进入飞智公众号, 了解更多产品信息及服务。

## 产品中有害物质的名称及含量

部件名称	有害物质					
	铅 (Pb)	汞 (Hg)	镉 (Cd)	六价铬 (Cr(VI))	多溴联苯 (PBB)	多溴二苯醚 (PBDE)
印刷电路板组件	○	○	○	○	○	○
外壳	○	○	○	○	○	○
包装	○	○	○	○	○	○
线材	○	○	○	○	○	○
聚合物电池	○	○	○	○	○	○
硅胶	○	○	○	○	○	○
金属、胶带、等小结构件	○	○	○	○	○	○

本表格依据SJ/T 11364-2014的规定编制。

- 表示该有害物质在该部件所有均质材料中的含量均在GB/T 26572-2011规定的限量要求以下。
- × 表示该有害物质至少在该部件的某一均质材料中的含量超出GB/T 26572-2011规定的限量要求。



本标识内数字标识产品在正常使用状态下的环保使用期限为10年。

## 保修说明

自用户购买之日起15天内出现质量问题，直接联系购买店铺，进行退货或者更换同型号新产品。

## Federal Communications Commission (FCC) Statement

---

The device has been evaluated to meet general RF exposure requirement. The device can be used in portable exposure condition without restriction Federal Communication Commission (FCC) Radiation Exposure Statement Power is so low that no RF exposure calculation is needed.

This device complies with part 15 of the FCC rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation.

Note: The manufacturer is not responsible for any radio or TV interference caused by unauthorized modifications or changes to this equipment. Such modifications or changes could void the user's authority to operate the equipment.

Note: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/ TV technician for help.